

PGM-111 USB driver installation guide

For Windows2000 and WindowsXP, follow the steps below to install driver.

1. Run **PL-2303Driver Installer.exe**
2. If you've installed an old version driver, then the following picture may appear. Press **“Re-install (Upgrade)”**



3. If there appears window below, press **“Continue Anyway”**.



4. Press **“Finish”**.



For Windows XP, further steps are needed.

5. Plug-in PGM-111.(If you've plugged it, unplug and then re-plug.)

6. There will come out a "Found New Hardware" window as below.

Select **"Install the software automatically"** and press **"Next"**.



7. Press **"Continue Anyway"** after the window below appears.



8. You will see the OS is copying the driver.



9. Press “**Finish**”.



Till now, the PGM-111 USB driver has been installed successfully. You can check it by Device Manager as shown below.



For Windows XP, plugging PGM-111 into different USB ports needs to repeat steps 5 ~9.

If you failed in installation, you can remove every possible PGM-111 driver installed before by running **PL-2303 Driver Installer.exe** and select “**Uninstall driver!**”. After re-start computer, repeat installation procedures as described above.